



2018 Engine Setback Bulletin (6/8/18)

Please note the new wording under the Engine Setback heading:

1. A maximum of 25 ½"-inches from the center of the ball joint to the front of the motor plate/engine bell housing flange.